


K/X Compatibility Kit


Instructions for Use

- Kit for GC20X-K, GI30X-K, ... detectors
- Ensures backward compatibility with GC20K, GC20PK, GI30K, GI30WK, ... detectors
- Allows use of the existing 4-pin connector
- Allows mounting on the old-style bracket



Installation Procedure

1. Remove the cover from the new detector.
2. Secure the bracket to the bottom of the detector using the four screws and nuts, with the nuts on the upper side. Orient the bracket so that the clip points towards the sensor head.



3. Set the jumpers on the detector.
4. Refit the detector cover.
5. Secure the interconnecting cable.



J.T.O. System, s.r.o.

1. máje 823

756 61 Rožnov pod Radhoštěm

<https://www.jto.cz>

Telephone:

+420 602 546 347

+420 775 646 347

posta@jto.cz